



ENGLISH

Datasheet

Stock No. 123-2210

RS-1260

## Humidity Temperature Meter



### FEATURES

- Dual LCD display.
- Dew Point Reading.
- Wet bulb Reading.
- MAX/MIN with Time Stamp.
- Data Hold function.
- °C / °F Switchable.
- DATA memory and read function.  
(99 readings from LCD display)
- Auto Power Off.

## SPECIFICATIONS

<b>Measuring Range</b>	Temperature : -20 to 60°C (-4 to 140°F) Humidity : 1%RH to 99%RH
<b>Resolution</b>	0.1°C /0.1°F /0.1%RH
<b>Accuracy</b>	Temperature : $\pm 0.5^{\circ}\text{C}$ , $\pm 0.9^{\circ}\text{F}$ Humidity : $\pm 3\% \text{RH}$ ( at 25°C, 30 to 99% RH ) $\pm 5\% \text{RH}$ ( at 25°C, 1 to 30% RH )
<b>Data Memory capacity</b>	Manual recording : 99 data sets. (Direct reading from LCD display.)
<b>Sampling Rate</b>	2 times per second
<b>Operating Conditions</b>	0 to 60°C (32 to 140°F) & below 99% R.H. (no condensation)
<b>Power Source</b>	9V Battery
<b>Battery Life</b>	Approx. 300 hours
<b>Size &amp; Weight</b>	193x59x26mm / 140g
<b>Accessories</b>	Instruction manual, Battery